AD-A236 217

Final Report
MAY 1989

EVT 8-89

EVALUATION OF PREFABRICATED ALUMINUM DUNNAGE IN A RAIL AND ROAD TRANSPORTATION ENVIRONMENT

DISTRIBUTION STATEMENT A

Approved for public poleone Distribution United SUNO 4 1991)

Distribution Unlimited

Prepared For.

Navai Weapons Station, Earle

Code: 8021

Colts Neck, NJ 07722

91-00959

91 5 31 035

EVALUATION DIVISION SAVANNA, ILLINOIS 61074-9639



US ARMY DEFENSE AMMUNITION CENTER AND SCHOOL

AVAILABILITY NOTICE

A complimentary copy of this report is furnished each attendee on automatic distribution. Additional copies or authority for reprinting may be obtained by written request from Director, U.S. Army Defense Ammunition Center and School, ATTN: SMCAC-DEV, Savanna, IL 61074-9639.

DISTRIBUTION INSTRUCTIONS

Destroy this report when no longer needed. Do not return.

* * *

Citation of trade names in this report does not constitute an official endorsement.

* * *

The information contained herein will not be used for advertising purposes.

SECURITY CLASSIFICATION OF THIS PAGE

REPORT DOCUMENTATIO			N PAGE			Form Approved OMB No. 0704-0188			
	SECURITY CLAS	SIFICATION		1b. RESTRICTIVE	MARKINGS				
	2a. SECURITY CLASSIFICATION AUTHORITY			3. DISTRIBUTION/AVAILABILITY OF REPORT					
2b. DECLASSI	FICATION / DOV	NNGRADING SCHEDU	JLE	UNLIMITE	D				
4. PERFORMI	NG ORGANIZAT	TION REPORT NUMBI	ER(S)	5. MONITORING	ORGANIZATION	REPORT N	UMBER(S)		
EVT 8-	89								
6a. NAME OF PERFORMING ORGANIZATION U.S. Army Defense Ammunition Center and School SMCAC-DEV				7a. NAME OF M	ONITORING ORG	ANIZATION			
6c. ADDRESS	(City, State, an	id ZIP Code)		7b. ADDRESS (Ci	ty, State, and ZII	Code)			
	SMCAC-DEV a, IL 610								
ORGANIZ		ONSORING Station, Earle	8b. OFFICE SYMBOL (If applicable)	9. PROCUREMEN	T INSTRUMENT I	DENTIFICA	TION NUMBER		
	City, State, and		code oozi	10. SOURCE OF	ELINDING NUMBE	90			
Code 8	-	ir coe,		PROGRAM	PROJECT	TASK	WORK UNIT		
	Neck, NJ	07722		ELEMENT NO.	NO.	NO.	ACCESSION NO.		
11. TITLE (Inc.	ude Security C	(lassification)		<u> </u>	1				
	•	·	Aluminum Dunnage	in a Rail a	nd Road Tra	nsporta	ation Environment		
12. PERSONAI									
	McIntosh,	Jr.							
13a. TYPE OF FINAL	REPORT	13b. TIME C FROM	OVERED TO	14. DATE OF REPORT (Year, Month, Day) 15. PAGE COUNT 1989 May 43					
16. SUPPLEME	NTARY NOTA	TION							
17.	COSATI	CODES	18. SUBJECT TERMS (Continue on reven	se if necessary ar	nd identify	by block number)		
FIELD	GROUP	SUB-GROUP							
			4						
19. ABSTRACT	(Continue on	reverse if necessary	and identify by block n	umber)					
The U.S. Army Defense Ammunition Center and School (USADACS), Evaluation Division (SMCAC-DEV), has been tasked by the U.S. Naval Weapons Station, Earle to evaluate a Navy suggestion to use aluminum dunnage which can be recycled as a replacement for wood. This suggestion was developed at an overseas command where dunnage lumber is expensive and difficult to obtain. Railroad impact and truck transportation tests of differing 500-pound bomb load configurations restrained by different configurations of prefabricated aluminum dunnage were conducted. These tests were accomplished using a flatear and a flat bed trailer. All test configurations passed the road transportation tests. Rail impact tests: The bulkhead restraint was able to keep six bomb units in place up to									
■ UNCLAS	SIFIED/UNLIMIT	TED 🗆 SAME AS	RPT. DTIC USERS	UNCLASS	IFIED		SEICE SYMBOL		
			ation Division	22b. TELEPHONE (Include Area Code) 22c. OFFICE SYMBOL 815-273-8080 SNGAC-DEV					
00 (44	73 IIIN 86		Province editions are	a handada	000000	- CLASSICI	TATION OF THIS PAGE		

19. Abstract (CONT)

6 miles per hour (mph) but started to deform (100 percent nailing). With 50 percent nailing, the bulkhead restraint unit became separated from the flatcar. Testing of the 'E' frame was unsuccessful because the unit load configuration was not rigid enough. End bracing for this unit is required.

The use of aluminimum dunnage which can be recycled has the potential of saving the Army and Navy lumber dunnaging expenses. In the case of road transportation, aluminum dunnage satisfied the road transportation tests.

A query of the overseas commands (Europe and Asia) should be made to assess the feasibility of using aluminum dunnage as an alternative for wood. The cost of lumber in Europe is expensive and the humid conditions of Asia cause wood to deteriorate and require constant maintenance.

U.S. ARMY DEFENSE AMMUNITION CENTER AND SCHOOL Evaluation Division Savanna, IL 61074-9639

REPORT NO. EVT 8-89

EVALUATION OF PREFABRICATED ALUMINUM DUNNAGE IN A RAIL AND ROAD TRANSPORTATION ENVIRONMENT

TABLE OF CONTENTS

PART			PAG	E NO
1.	INT	RODUCTION		1-1
	A.	Background	• • •	1-1
	В.	Authority		1-1
	C.	Objective		1-2
	D.	Conclusions		1-2
	E.	Recommendations		1-2
	F.	Approval		1-2
2.	ATT	ENDEES		2-1
3.	TES	T PROCEDURES		3-1
4.	TES	T RESULTS		4-1
5.	РНО	TOGRAPHS		5-1

PART 1

INTRODUCTION

A. BACKGROUND

The U.S. Army Defense Ammunition Center and School (USADACS), Evaluation Division (SMCAC-DEV), was tasked by the U.S. Naval Weapons Station, Earle (Code 8021) to evaluate a Navy suggestion to use aluminum as an alternative to wood dunnage. This suggestion was developed at an overseas command where lumber dunnage is expensive and difficult to obtain. The original intent of this suggestion was for the replacement of wood for intra-installation movement of ammunition by truck or rail. To evaluate these conditions, inert 500-pound bomb pallets were used in differing load configurations for over the road and rail transportation. The test were accomplished using a standard flatcar and a flatbed semitrailer.

B. AUTHORITY

This test was conducted in accordance with mission responsibilities delegated by the U.S. Army Armament, Munitions and Chemical Command (AMCCOM), Rock Island, IL. Reference is made to Change 4, 4 October 1974, to AR-740-1, 23 April 1971, Storage and Supply Operations; AMCCOM-R 10-17, 13 January 1986, Mission and Major Functions of USADACS.

C. OBJECTIVE

The objective of these tests was to determine if the aluminum dunnage would be a suitable replacement for wood dunnage in a road and rail transportation environment. The tests performed on different 500-pound bomb load configurations were: Rail Impact Test, Hazard Course, Road Trip and Washboard Course.

D. CONCLUSIONS

All test configurations passed the road transportation tests (hazard, road, and washboard). Rail Impact Tests: The bulkhead restraint was able to keep six bomb units in place up to six mph but started to deform (100 percent nailing). With 50 percent nailing, the bulkhead restraint separated from the flatcar. Testing of the 'E' frame was unsuccessful because the unit load configuration was not rigid enough. End bracing for this unit is required.

E. RECOMMENDATIONS

- 1. The use of aluminum dunnage which can be recycled has the potential of saving the Navy and Army lumber dunnaging expenses. In the case of road transportation, aluminum dunnage satisfied the road transportation tests.

 More investigation of aluminum dunnage techniques is required before it can be useful in a rail transportation environment.
- 2. A query of the overseas commands (Europe and Asia) should be made to assess the feasibility of using aluminum dunnage as an alternative to wood. The cost of lumber in Europe is expensive and the humid conditions of Asia cause wood to deteriorate and require constant maintenance.

F. APPROVAL

Approved for road transport upon U.S. Naval Weapons Station, Earle publication of Navy procedure.

PART 2

ATTENDEES

Mr. A. C. McIntosh, Jr. Test Engineer AV 585-8989 815-273-8989

Mr. Quinn Hartman General Engineer AV 585-8992 815-273-8992

Mr. Robert Richard AV 449-2843 201-577-2843

Mr. John A. Green Assistant Chief Engineer 202-639-2357

Mr. Dan Healy District Inspector 312-359-0886 Director
U.S. Army Defense Ammunition Center and School
ATTN: SMCAC-DEV 815-273-8989

Savanna, IL 61074-9639

Director
U.S. Army Defense Ammunition Center
and School
ATTN: SMCAC-DEV
Savanna, IL 61074-9639

Commanding Officer
U.S. Naval Weapons Station, Earle
CODE: 8021-RAR
Colts Neck, NJ 07722-5000

Association of American Railroads Freight Claim and Damage Prevention Division 50 F Street NW Washington, DC 20001

Association of American Railroads/ Bureau of Explosives Hazardous Materials 50 F Street NW Washington, DC 20001



Access	ion For	
NTIS DTIC T Unamed Justif	AB	
	ibutfon	/ y Codes
1	Avail s Speci	nd/or

PART 3

TEST PROCEDURES

A. RAIL IMPACT TEST.

The test load or vehicle should be positioned in/on a railcar. For containers, the loaded container shall be positioned on a container chassis and securely locked in place using the twist locks at each corner. The container chassis shall be secured to a railcar. Equipment needed to perform the test includes the specimen (hammer) car, five empty railroad cars connected together to serve as the anvil, and a railroad locomotive. These anvil cars are positioned on a level section of track with air and hand brakes set and with the draft gear compressed. The locomotive unit pulls the specimen car several hundred yards away from the anvil cars and, then, pushes the specimen car toward the anvil at a predetermined speed, disconnects from the specimen car about 50 yards away from the anvil cars and allows the specimen car to roll freely along the track until it strikes the anvil. constitutes an impact. Impacting is accomplished at speeds of 4, 6, and 8 mph in one direction and at a speed of 8 mph in the opposite direction. The 4 and 6 mph impact speeds are approximate; the 8 mph speed is a minimum. Impact speeds are to be determined by using an electronic counter to measure the time required for the specimen car to traverse an 11 foot distance immediately prior to contact with the anvil cars.

B. HAZARD COURSE.

The specimen being tested will be subjected to the road hazard course.

Using a suitable truck/tractor or tactical vehicle, the vehicle/specimen of test method No. A shall be towed/driven over a hazard course two times at a

speed of approximately 5 mph. The speed may be increased or decreased, as appropriate, to produce the most violent load response.

C. ROAD TRIP.

Using a suitable truck/tractor and trailer, or tactical vehicle, the tactical vehicle/specimen load shall be towed/driven for a total distance of at least 30 miles over a combination of roads surfaced with gravel, concrete, and asphalt. Test route shall include curves, corners, railroad crossings, cattle guards, stops, and starts. The test vehicle shall travel at the maximum speed suitable for the particular road being traversed, except as limited by legal restrictions. This step provides for the tactical vehicle/specimen load to be subjected to three full airbrake stops while traveling in the forward direction and one in the reverse direction while traveling down a 7 percent grade. The first three stops are at 5, 10, and 15 mph, while the stop in the reverse direction is of approximately 5 mph.

D. WASHBOARD COURSE.

Using a suitable truck/tractor, and/or tactical vehicle, the specimen shall be towed/driven over the washboard course at a speed which produces the most violent response in the particular test load (as indicated by the resonant frequency of the suspension system beneath the load).

PART 4

TEST RESULTS


TEST RESULTS

TEST NO. 1 DATE: 22 FEBRUARY 1989


TEST SPECIMEN: Flatcar with Aluminum Bulkhead, Two Pallets of 500-pound Bombs and Aluminum 'E' Frame. 50 percent Nailed.

TEST CAR NO. SP&S 34085	LT. WT.	47,100	pounds
LADING AND DUNNAGE	WT.	7,000	pounds
TOTAL SE	PECIMEN WT.	54,100	pounds
BUFFER CAR (5	5 CARS) WT	220 000	nounde

IMPACT NO.	END STRUCK	VELOCITY (MPH)	IMPACT FORCE	REMARKS
1	forward	5.51	187,000	no damage
2	forward	6.94	306,000	no damage
3	forward	8.38	394,000	no damage
4	reverse	8.92	439,000	no damage



Time in Seconds X 1.00



Time in Seconds

X 1.88

00.00001 X 20NUO9 NI

1.80 RAIL IMPACT TEST OF ALUMINUM DUNNAGE 02-22-89 8.38 MPH, DATE: <u>ო</u> IMPACT . 200 2.40 1.80 1.20 .000 .600

Time in Seconds


X 1.00

4-5

LOKCE

BO. BOBOOL X SUNDOY NI

CONSTER



(FILTERED)

4-6

Time in Seconds

X 1.00

KUIL

TEST RESULTS

TEST NO. 2

DATE: 22 FEBRUARY 1989

TEST SPECIMEN: Flatcar with Aluminum Bulkhead, Four Pallets of 500-pound Bombs and Aluminum "E" Frame. 50 percent Nailed.

TEST CAR NO. S	P&S 34085	LT.	WT.	47,100	pounds
LADING AND DUNNA	GE		WT.	13,000	pounds
	TOTAL	SPECIMEN	WT.	60,100	pounds
	BUFFER CAR	(5 CARS)	wr ·	220 000	nounde

IMPACT NO.	END STRUCK	VELOCITY (MPH)	IMPACT FORCE	REMARKS
1	forward	4.28	n.r.*	no damage
2	forward	7.02	n.r.	bulkhead separated from flatcar. All nails pulled out of flatcar deck.

^{*} impact force was not recorded.

TEST RESULTS

TEST NO. 3 DATE: 23 FEBRUARY 1989

TEST SPECIMEN: Flatcar with Aluminum Bulkhead, Four Pallets of 500-pound

Bombs and Aluminum 'E' Frame. 100 percent Nailed.

TEST CAR NO. SP&S 34085 LT. WT. 47,100 pounds

LADING AND DUNNAGE WT. 13,000 pounds

TOTAL SPECIMEN WT. 60,100 pounds

BUFFER CAR (5 CARS) WT. 220,000 pounds

IMPACT NO.	END STRUCK	VELOCITY (MPH)	IMPACT FORCE	REMARKS
1	forward	4.12	194,000	no damage
2	forward	6.52	165,000	no damage
3	forward	8.31	379,000	Exceeded structural limit of end gate. Aluminum angle deformed and corner weld broken.


RAIL IMPACT TEST OF ALUMINUM BUNNAGE 02-23-89 4.12 MPH, DATE: 1.00 IMPACT 1.60 1.20 .400 . 000 .808

4-9

-1

Time in Seconds

00.000001 X 20NUO9 NI



Time in Seconds

(FAILURE OCCURED) 1.80 RAIL IMPACT TEST OF ALUMINUM DUNNAGE 82-23-89 1.00 DATE: 8.31 MPH, .600 <u>ლ</u> .200 IMPACT 2.40 1.80 .600 1.20 . 888

Time in Seconds

X 1.00

TEST NO. 4 DATE: 23 FEBRUARY 1989

TEST SPECIMEN: Flatcar with Aluminum Bulkhead, 10 Pallets of 500-pound Bombs

and Aluminum 'E' Frame. 100 percent Nailed. Web Strap unit restraint.

TEST CAR NO. SP&S 34085 LT. WT. 47,100 pounds

LADING AND DUNNAGE WT. 32,000 pounds

TOTAL SPECIMEN WT. 79,100 pounds

BUFFER CAR (5 CARS) WT. 220,000 pounds

IMPACT NO.	END STRUCK	VELOCITY (MPH)	IMPACT FORCE	REMAKRS
1	forward	3.91	215,000	no damage
2	forward	6.46	264,000	Unit at position 2 and 3 racked. Broken Web Straps. Forward shift in pallets.

HRS 1.80 02-23-89, 1200 RAIL IMPACT TEST OF ALUMINUM DUNNAGE 1.40 3.91 MPH, DATE: 1.00 .600 IMPACT 1: . 200 1000 200. -200. -600. 600.

-1


Time in Seconds

IMPACT TEST OF ALUMINUM DUNNAGE 6.46 MPH, DATE: RAIL N IMPACT 1.20 2.40 1.80

HRS

1200

02-23-89,



Time in Seconds X 1.80

POUNDS

TEST NO. 5 DATE: 24 FEBRUARY 1989

TEST SPECIMEN: Flatcar with Aluminum Bulkhead, 10 Pallets of 500-pound Bombs and Aluminum 'E' Frame. 100 percent Nailed. (1-1/4-inch Banding Restraint.)

TEST CAR NO.	SP&S	34085			LT.	WT.	47,100	pounds
LADING AND DUN	IAGE					WT.	32,000	pounds
			TOTAL	SPECIMEN		WT.	79,100	pounds

BUFFER CAR (5 CARS) WT. 220,000 pounds

IMPACT NO.	END STRUCK	VELOCITY (MPH)	IMPACT FORCE	REMARKS
1	forward	4.60	178,000	no damage
2	forward	6.71	245,000	Units at position 2 and 3 racked. Banding straps broke. The 500-pound bomb pallets canted forward after impact. Further rail testing was stopped due to the instability of this test configuration.

LOKCE

RAIL IMPACT TEST OF ALUMINUM DUNNAGE 02-24-89 4.60 MPH, DATE: 1.00 IMPACT 1: .200 1.60 1.20 .800 .400 . 888

(LITTERED)

4-16

ı


Time in Seconds X 1.88

NI

CONDIER

4-17

00.000001 X 20NUO4 NI



Time in Seconds

ROAD TEST DATA

TEST NO. 6 DATE: 22 FEBRUARY 1989

TEST SPECIMEN: 500-pound Bombs, Aluminum Bulkhead and 'E' Restraint, M871

Semitrailer, Two Pallets One-layer High, Web Strap Restraint.

PASS 1-A OVER FIRST SERIES OF TIES: 0.09 MIN 6.3 MPH

PASS 1-B OVR SECOND SERIES OF TIES: 0.09 MIN 6.3 MPH

REMARKS: No damage or load movement.

PASS 2-A OVER FIRST SERIES OF TIES: 0.09 MIN 6.3 MPH

PASS 2-B OVER SECOND SERIES OF TIES: 0.09 MIN 6.3 MPH

REMARKS: No damage to load or load movement.

30 MILE ROAD TEST: No damage or load movement.

PANIC STOP TEST: No load movement or damage.

PASS 3-A OVER FIRST SERIES OF TIES: 0.10 MIN 5.7 MPH

PASS 3-B OVER SECOND SERIES OF TIES: 0.10 MIN 5.7 MPH

REMARKS: No movement.

PASS 4-A OVER FIRST SERIES OF TIES: 0.10 MIN 5.7 MPH

PASS 4-B OVER FIRST SERIES OF TIES: 0.10 MIN 5.7 MPH

REMARKS: No load movement or damage.

WASHBOARD COURSE: No movement or damage.

ROAD TEST DATA

TEST NO. 7 DATE: 22 FEBRUARY 1989

TEST SPECIMEN: 500-pound Bombs, Aluminum Bulkhead and 'E' Frame, M871 Semitrailer, Six Pallets (two-high by three-long) Web Strap Restraints, Units Banded Together Two-high with 2 by 6 Vertical Supports.

PASS 1-A OVER FIRST SERIES OF TIES: 0.09 MIN 6.3 MPH

PASS 1-B OVER SECOND SERIES OF TIES: 0.09 MIN 6.3 MPH

REMARKS: Lateral unit load movement in upper layer. Tore off lateral cleat. Replaced.

PASS 2-A OVER FIRST SERIES OF TIES: 0.10 MIN 5.7 MPH

PASS 2-B OVER SECOND SERIES OF TIES: 0.10 MIN 5.7 MPH

REMARKS: Bombs moving out of unitization.

30 MILE ROAD TEST: No additional movement.

PANIC STOP TEST: No movement or damage.

PASS 3-A OVER FIRST SERIES OF TIES: 0.10 MIN 5.7 MPH

PASS 3-B OVER SECOND SERIES OF TIES: 0.09 MIN 6.3 MPH

REMARKS: Lateral shifting of bombs in unit.

PASS 4-A OVER FIRST SERIES OF TIES: 0.09 MIN 6.3 MPH

PASS 4-B OVER SECOND SERIES OF TIES: 0.09 MIN 6.3 MPH

REMARKS: Lateral movement of bombs in unitization.

WASHBOARD COURSE: No additional lateral movement.

PART 5

PHOTOGRAPHS






Photo No. 1 (89-2623) This photo shows unitized 500-pound bombs on a railcar restrained railcar by the use of nuclear web straps. Note racking of the unit loads on the railcar. run of 2 by 4s with 2 by 6s recessed to hold the bottom skid of the bomb pallet in place. Also note the in-line dunnage required to restrain the unit loads being made up of one Bomb pallets were restrained to the by the aluminum prefabricated dunnage E frame.






Photo No. 3 (89-2620) This photo shows the aluminum E. frame with 100 percent nailing to the flatear deck. Note unitization restrain at the right-hand side of the pallot for incline blocking of a single aluminum angle.


·		H	İ
	=	•Jeuunp	
	SAVANNA,	e tau	
	SAV	1 .11	
		et e	
	SCHOOL-	bric	
	ည်	refa	
		be p	
	ANO	\$ 03	
	œ	This photo shows demage to the prefabricated aluminum rail transportation.	
	CENTER	dem tion	
	R	borte.	
	Z	transportation.	
	Ħ	pho	
	Ş	This in rail	
	AMMUNITION	- - - 1	
	- 1	2019 ting	
	DEFENSE	-08) -08)	
	띨	10 P	
	믜	# £ £	
		Photo No. 3 (80-2619) frame after impacting	
		64	
	1		





		aluminum dunnage E frame restraint after impact and also note these pallets were restrained with a 1-1/4-inch steel banding. Note the broken bands on the 4th and 5th pallets. No damage was sustained by the aluminum E frame; however, severe racking of the ammunition pallets due to columnar loading and insufficient strength in the unitization.
--	--	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------


		of hold a
		IA, IL sade out consecut to he frame to
		SAVANNA Sement ma tps are u
		MMUNITION CENTER AND SCHOOL - SAVANNA, IL This photo shows a truss and blocking arrangement made out of 500-pound bomb pallet on a flatcar. Web straps are used to hold Fifty percent nailing was used to attach the 'A' frame to the
		ID SCH d blocki latear used to
		truss and to
		Shows a trustomb pallet on reent nailing
		MMUNITION CENTER This photo shows a truss 1 500-pound bomb pallet on 1r. Fifty percent nailing
		2
		OEFENSE AIO. 6 (89-2616) m restraining a
		Photo Bo. 6 (89-2616) aluminum restraining a pallet onto the flatcar flatcar deck.
		SM41 46 Chg Nog















DEFENSE AMMUNITION CENTER AND SCHOOL- SAVANNA, IL

The En. 12 (89-2596) This photo shows the forward end of a two-high 500-pound bomb smit load on a MS71 trailer after going over the road hazard course. The load shifted towards the rear approximately 1/2 inch.



5-14